

Inspection Photos

September 25th, 2024

Operator: American Helium Operating - 10841

Location ID: 322101

Inspection Document #: 714001270

Dolores County, CO

Township: SWNW 19 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Federal 2-19
Location ID: 322101

9/25/24
+37.646769,-108.957367
324° NW



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Federal 2-19
Location ID: 322101




Photo 2. Tank label needs to be updated. Weedy debris/vegetation are affecting secondary containment/berm integrity.

Inspection Photos
Location Name: Federal 2-19
Location ID: 322101



Photo 3. Within 25 feet insure that well heads and separators are free of combustible materials.

Inspection Photos
Location Name: Federal 2-19
Location ID: 322101

9/25/24
+37.839737,-109.462326
151° SE



Photo 4. View of western interim reclamation area that appears consistent with adjacent reference area.

Inspection Photos
Location Name: Federal 2-19
Location ID: 322101



Photo 5. Reference area comprised of Juniper, Indian ricegrass and Antelope bitterbrush.