

Inspection Photos

September 25th, 2024

Operator: American Helium Operating - 10841

Location ID: 381594

Inspection Document #: 714001272

Dolores County, CO

Township: SESE 19 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ranger Federal 16-19
Location ID: 381594

9/25/24
+37.619969,-108.979512
6° N



Photo 1. View of the well pad taken from the southern edge facing center.

Inspection Photos
Location Name: Ranger Federal 16-19
Location ID: 381594



Photo 2. Weeds on are affecting integrity of berm and need to be removed.



Inspection Photos
Location Name: Ranger Federal 16-19
Location ID: 381594

9/25/24
+37.620224,-108.979446
270° W



Photo 3. View of northern portion of the interim reclamation.

Inspection Photos
Location Name: Ranger Federal 16-19
Location ID: 381594

9/25/24
+37.620316,-108.979446
336° NW



Photo 4. Adjacent reference area comprised of a harvested ag field.