

# Inspection Photos

September 25th, 2024

Operator: Forest Oil Corporation - 30450

Location ID: 381583

Inspection Document #: 714001273

Dolores County, CO

Township: NESE 27 39N 20W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Annie Federal 1  
Location ID: 381583



9/25/24  
+37.839737, -109.462326  
107° E




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the project area taken from the western edge facing center.

API #: 033-06077



Inspection Photos  
Location Name: Annie Federal 1  
Location ID: 381583



**Photo 2.** View of transects conducted at the location, Disturbed area (left) and reference area (right).



Inspection Photos  
Location Name: Annie Federal 1  
Location ID: 381583



9/25/24  
+37.609895,-109.032678  
0° N



9/25/24  
+37.609895,-109.032678  
233° SW

**Photo 3.** View of access road that remains unreclaimed.



Inspection Photos  
Location Name: Annie Federal 1  
Location ID: 381583



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of reference area comprised of Sagebrush, Indian ricegrass and Broom snakeweed.

API #: 033-06077