

Inspection Photos
Location Name: ROTHE-65N63W/29SESW
Location #: 306705



Photo #1
Rothe 24-29U (123-25137) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 35 yds.



Photo #2
Rothe 29BU, 13-29U, 14-29U, 23-29U, 24-29U
Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA (5-Wells)

