

Inspection Photos
Location Name: SIEBRING-65N63W/29SWSE
Location #: 332785



Photo #1
Siebring 33-29DU (123-29555) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 35 yds.



Photo #2
West Hardin #1, Siebring 34-29U, 33-29DU, 29-PU
Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA (4-Wells)

