

Inspection Photos


Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



Entrance to location - Photo #06195



Location - Photo #06194

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



Location - Photo #06197



Location - Photo #06199

Inspection Photos


Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



Location - Photo #06210



SW corner of location - Photo #06217

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



SE corner of location - Photo #06218



Wildlife hazard - Photo #06200

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



No labeling - Photo #06216

Debris - Photo #06221

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW

Location ID: 324306

Date: 9/23/2024



Debris - Photo #06222

