

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530




Photo # 2341 From entrance to location

Photo # 2342 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeffli RWF 32-36 Pad

Location ID: 335530



Photo # 2343 Location



Photo # 2344 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2345 Location



Photo # 2346 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Sep 26, 2024 at 1:02:54 PM  
CO



Sep 26, 2024 at 1:05:26 PM  
CO

Photo # 2347 Location

Photo # 2348 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2349 Location



Photo # 2350 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2351 Spill response station



Photo # 2352 Stored trailer on location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2353 Stored generator on location



Photo # 2354 Stored shipping container, snowmobiles & misc on location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2355 Stored logs on location



Photo # 2356 Stored misc & Improperly stored fuel container on location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad

Location ID: 335530



Photo # 2357 Debris