

Inspection Photos
Location Name: John Horst B #1
Location ID: 318553



Photo 1: Location from entrance



Photo 2: Overgrown vegetation around ancillary equipment

Inspection Photos
Location Name: John Horst B #1
Location ID: 318553



Photo 3: Overgrown vegetation around ancillary equipment



Photo 4: Wellhead Sign

Inspection Photos
Location Name: John Horst B #1
Location ID: 318553



Photo 5: Overgrown vegetation



Photo 6: Overgrown vegetation

Inspection Photos
Location Name: John Horst B #1
Location ID: 318553



Photo 7: Overgrown vegetation