

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 1: Location from entrance



Photo 2: Overgrown vegetation NW of location

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 3: Overgrown vegetation NW of location



Photo 4: Trash outside treater fencing

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 5: Overgrown vegetation outside/inside of fencing.



Photo 6: Overgrown vegetation

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 7: Overgrown vegetation



Photo 8: Trash W of location

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 9: Overgrown vegetation



Photo 10: Tank Battery Sign

Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 11: No contents/capacity




Photo 12: No contents/capacity



Inspection Photos
Location Name: Cleveland #7 Tank Battery
Location ID: 336113



Photo 13: Overgrown vegetation



Photo 14: No bird protector