

**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 1: Location from entrance**



**Photo 2: Overgrown vegetation**



Inspection Photos  
Location Name: Walter Hunziker #1  
Location ID: 317632



Photo 3: Tank Battery Sign



Photo 4: Overgrown vegetation





**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 5: Overgrown vegetation**



**Photo 6: Overgrown vegetation**



**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 7: Overgrown vegetation**



**Photo 8: Earthen berm not maintained**



**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 9: Earthen berm not maintained**



**Photo 10: Earthen berm not maintained**



**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 11: Overgrown vegetation**



**Photo 12: No annual calibration**

**Inspection Photos**  
**Location Name: Walter Hunziker #1**  
**Location ID: 317632**



**Photo 13: Wellhead Sign**



**Photo 14: Overgrown vegetation**