

Inspection Photos
Location Name: Martin T. Hart #3
Location ID: 318872



Photo 1: Location from entrance, overgrown vegetation



Photo 2: Wellhead sign

Inspection Photos
Location Name: Martin T. Hart #3
Location ID: 318872



Photo 3: Overgrown vegetation



Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Martin T. Hart #3
Location ID: 318872



Photo 5: Overgrown vegetation