

**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 1: Tank Battery, Overgrown vegetation, no battery sign, no tank sign**



**Photo 2: Berm not maintained, overgrown vegetation**



**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 3: Berm not maintained, no sign on tank**



**Photo 4: No sign on tank (capacity/contents/NFPA)**



Inspection Photos  
Location Name: Martin T. Hart #1  
Location ID: 317639



Energy & Carbon Management Commission  
40.10865, -104.87964, 1509.0m, 35°  
Sep 27, 2024 12:07:17

Photo 5: Berm not maintained, overgrown vegetation



Energy & Carbon Management Commission  
40.10889, -104.87968, 1510.5m, 144°  
Sep 27, 2024 12:08:34

Photo 6: Meter not annually calibrated.



**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 7: Overgrown vegetation**



**Photo 8: Overgrown vegetation**



Inspection Photos  
Location Name: Martin T. Hart #1  
Location ID: 317639



Photo 9: Meter not annually calibrated



Photo 10: Overgrown vegetation



**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 11: Overgrown vegetation**



**Photo 12: Overgrown vegetation**



**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 13: Wellhead Sign**



**Photo 14: Overgrown vegetation**

**Inspection Photos**  
**Location Name: Martin T. Hart #1**  
**Location ID: 317639**



**Photo 15: Overgrown vegetation**