

# Interim Reclamation and Stormwater Inspection

Date: 9/27/24

Operator: PDC Energy Inc - 69175

Location ID: 447046

Inspection Document #: 713901022

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

# Inspection Photos

Location Name: Werning 01-02B, 08-03B,  
41-03B

Location ID: 447046



**Photo 1.** The photo was taken at the entrance to the tank battery location facing Northwest. The photo illustrates the Operator location sign.



**Photo 2.** The photo was taken at the tank battery location facing Northeast. The photo illustrates the South side of the tank battery facility.



# Inspection Photos

Location Name: Werning 01-02B, 08-03B,  
41-03B

Location ID: 447046



**Photo 3.** The photo was taken at the tank battery location facing Northwest. The photo illustrates the West side of the tank battery facility with tumbleweed growth along the fenceline.



**Photo 4.** The photo was taken at the tank battery location facing East. The photo illustrates the North side of the tank battery facility with tumbleweed growth along the fenceline.



Inspection Photos

Location Name: Werning 01-02B, 08-03B,  
41-03B

Location ID: 447046



**Photo 5.** The photo was taken at the tank battery facility facing North. The photo illustrates wattle on the North side of the pad that needs repaired or replaced.

Note - The photo is representative for wattle on the West side that needs maintenance.



Inspection Photos

Location Name: Werning 01-02B, 08-03B,  
41-03B

Location ID: 447046



**Photo 6.** The photo was taken at the tank battery facility facing Northwest. The photo illustrates stained soil on the production pad.