

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



Entrance to location - Photo #06300



Location - Photo #06307

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



Sep 25, 2024 at 12:31:36 PM
+39.421445,-108.099869 ±4.73m
De Beque



Sep 25, 2024 at 12:32:12 PM
+39.421539,-108.099902 ±4.72m
De Beque

Location - Photo #06301

Location - Photo #06302

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



Location - Photo #06310

Location - Photo #06311

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



Sep 25, 2024 at 12:53:34 PM
+39.421783,-108.099697 ±4.71m
De Beque



Sep 25, 2024 at 1:06:24 PM
+39.421480,-108.099988 ±4.71m
De Beque

Location - Photo #06312

No tank battery sign - Photo #06330

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



Stockpiled road base with no BMP's - Photo #06337



NW corner of location - Photo #06338

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIGHT BOTTOM RANCH/SG 23-22

Location ID:435460

Date: 9/25/2024



NE corner of location - Photo #06339