

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/36B-795

Location ID: 324310

Date: 9/26/2024



Wellhead – Photo #03716



Separator – Photo #03718

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/36B-795

Location ID: 324310

Date: 9/26/2024



Tank Battery – Photo #03719



Lack of Stabilization with No Tracking BMP – Photo #03717