

Inspection Photos  
Location Name: Cleveland #8  
Location ID: 332926



Photo 1: Location from entrance, overgrown vegetation.

Photo 2: Wellhead Sign

**Inspection Photos**  
**Location Name: Cleveland #8**  
**Location ID: 332926**



**Photo 3: Storage of equipment**

**Photo 4: Overgrown vegetation**

Inspection Photos  
Location Name: Cleveland #8  
Location ID: 332926



Photo 5: Unused/disconnected equipment



Photo 6: Overgrown vegetation