

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location #: 324099



Photo # 2875 From entrance to location

Photo # 2876 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location #: 324099



Sep 30, 2024 at 1:05:21 PM



Sep 30, 2024 at 1:07:29 PM


Photo # 2877 Location

Photo # 2878 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location #: 324099



Sep 30, 2024 at 1:08:15 PM



Sep 30, 2024 at 1:15:10 PM

Photo # 2879 Location

Photo # 2880 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location #: 324099



Photo # 2881 Unmarked deadman

Photo # 2882 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location #: 324099




Photo # 2883 Tank labeled inaccurately/capacity incorrect

Photo # 2884 Tank capacity