



Inspection Photos

Location Name: Fletcher Gulch 3-22

Location ID: 316579

Spill/Release ID: 485092

Inspection Date: September 24, 2024

Meter shack.

Sep 24, 2024 12:20:35 PM  
+40.0860N -108.6057W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-22

Location ID: 316579

Spill/Release ID: 485092

Inspection Date: September 24, 2024

Wellhead and pumpjack.

Sep 24, 2024 12:21:33 PM  
+40.0862N -108.6056W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-22

Location ID: 316579

Spill/Release ID: 485092

Inspection Date: September 24, 2024

Wellhead, note the impacts adjacent to the wellhead.

Sep 24, 2024 12:21:44 PM  
+40.0862N -108.6054W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Fletcher Gulch 3-22

Location ID: 316579

Spill/Release ID: 485092

Inspection Date: September 24, 2024

Impacts observed on the location related to Spill/Release 485092 and potentially other spill/releases originating at the wellhead

Sep 24, 2024 12:21:00 PM  
+40.0861N -108.6056W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Inspection Photos**

**Location Name: Fletcher Gulch 3-22**

**Location ID: 316579**

**Spill/Release ID: 485092**

**Inspection Date: September 24, 2024**

Areas northwest of the location where impacts traveled off the well pad and down a ditch adjacent to the lease road.

Sep 24, 2024 12:21:14 PM  
+40.0862N -108.6058W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources