

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 487592

Inspection Doc: 69620639

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 487592



Photo 1: Photo left taken from the intersection of the public/lease road. Photo right shows only sign observed along the access road. Signage pursuant to Rule 406.d has not been posted.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 487592



Photo 2: Location signage. Form 2A permit information posted in tube.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 487592



Photo 3: Equipment mobilized along access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 487592



Photo 4: Photos examples showing Operator in process of installing erosion logs along the perimeter of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 487592



Photo 5: Photo example of topsoil horizon(s) on Location- there are areas where topsoil depths exist up to 27 inches in depth.