

Inspection Photos
Location Name: Crossland 2-1
API Number: 125-09819



1. Well sign at wellhead.



2. View of wellhead. Note vegetation growth around well.

Inspection Photos
Location Name: Crossland 2-1
API Number: 125-09819



3. View of possible Bradenhead piping with no valve or fittings.



4. Sign at produced water tank. Note sign is peeling and labels require replacement.

Inspection Photos
Location Name: Crossland 2-1
API Number: 125-09819



5. Vertical separator inside shed.



6. Gas meter inside meter shed.

