

Final Reclamation and Stormwater Inspection

Date: 09/27/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 306751

Inspection Document #: 708201641

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751



Photo 1. Undesirable vegetation previously observed along the access road appears to have been managed for.

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751



Photo 2. Facing north near the former well location. It appears that undesirable vegetation has been managed by mowing operations.

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751



Photo 3. Facing east; see comments in Photo 2.

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751



Photo 4. Facing south; see comments in Photo 2.

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751



Photo 5. Facing west; see comments in Photo 2.

Inspection Photos
Location Name: Callen USX N27-2
Location ID: 306751




Photo 6. Meter sheds remain on location; red arrows indicate Kerr Mcgee meter sheds. Additionally, undesirable vegetation has been managed for around the former tank battery location.