

# Inspection Photos

API: 099-06868

Operator: LAMAR OIL & GAS EXPLORATION

Inspection Date: 9/24/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing northeast toward the wellsite location.



## Inspection Photos



**Photo 2.** Center of the location facing north.



## Inspection Photos



**Photo 3.** Center of the location facing west.



## Inspection Photos



**Photo 4.** Center of the location facing south.



## Inspection Photos



**Photo 5.** North side of the location facing southeast. This area does not have sufficient vegetation cover.



## Inspection Photos



**Photo 6.** There is still wood debris that remains onsite.

