



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Calamity Ridge 14-31
Location.

Sep 24, 2024 11:16:52 AM
+40.0539N -108.5909W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Unused equipment.

Sep 24, 2024 11:17:02 AM
+40.0539N -108.5910W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Unused equipment, trash
and debris.

Sep 24, 2024 11:18:57 AM
+40.0540N -108.5910W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Pumpjack.

Sep 24, 2024 11:17:49 AM
+40.0540N -108.5912W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Calamity Ridge 14-31

Location ID: 423560

Inspection Date: September 24, 2024

Wellhead.

Sep 24, 2024 11:18:41 AM
+40.0541N -108.5914W



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Meter house.

Sep 24, 2024 11:17:13 AM
+40.0539N -108.5911W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Tank battery secondary
containment structure.

Sep 24, 2024 11:17:21 AM
+40.0540N -108.5911W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Tank battery.

Sep 24, 2024 11:17:10 AM
+40.0539N -108.5911W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Calamity Ridge 14-31
Location ID: 423560
Inspection Date: September 24, 2024

Steel AST with TEP
Rocky Mountain LLC
signage.

Sep 24, 2024 11:17:39 AM
+40.0539N -108.5911W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources