

Inspection Photos
Location Name: Crossland 3-1
API Number: 125-10987



1. Well sign at well location.



2. View of wellhead. Note vegetation inside fencing. Note white PVC pipe at center of frame.

Inspection Photos
Location Name: Crossland 3-1
API Number: 125-10987



3. Well location overview.



4. Vertical separator inside separator shed.

Inspection Photos
Location Name: Crossland 3-1
API Number: 125-10987



5. Gas meter inside meter shed.



6. Location overview.