

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 1 – Barbed Wire blocking Access Road to Well

Photo 2 – Well to the East of Tank Battery Location

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 3 – Heater Treater – Weeds



Photo 4 – Heater Treater

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 5 – Battery Sign



Photo 6 – Unused Black Barrel

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 7 – Tank Battery



Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 9 – Tank Labels

Photo 10 – Pit Area – Weeds

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 11 – Location Overview – Weeds