

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403944581

Date Received:

10/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001068

Inspection Date: 08/12/2024

FIR Submit Date: 08/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333113

Location Name: SOUTHERN UTE GAS UNIT- N32N10W Number: 12SENE County: _____

Qtrqr: SENE Sec: 12 Twp: 32N Range: 10W Meridian: N

Latitude: 37.033990 Longitude: -107.880158

FACILITY - API Number: 05-067- -00 Facility ID: 333113

Facility Name: SOUTHERN UTE GAS UNIT- N32N10W Number: 12SENE

Qtrqr: SENE Sec: 12 Twp: 32N Range: 10W Meridian: N

Latitude: 37.033990 Longitude: -107.880158

CORRECTIVE ACTIONS:

1 CA# 197707

Corrective Action: Comply with rule 606, remove and properly dispose of weedy debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 09/12/2024

Operator
Comment:

Weedy debris removed from location and kochia/Russian Thistle chemically sprayed.

ECMC Decision: _____

New Label put on tank.

CA complete. See attached photos.

Signed: _____

Date: 10/3/2024 10:46:46 AM

Total Attach: 1 Files