

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 1 – Wellhead



Photo 2 – Well Sign

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 3 – Pumping Unit



Photo 4 – Pit Area

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 5 – Pit Area



Photo 6 – Heater Treater

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 7 – Skim Tank – Missing Tank Labels



Photo 8 – Heater Treater and Gas Meter

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 9 – Tank Battery – Berms Inadequate



Photo 10 – Tank Battery – Berms Inadequate

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 11 – Tank Battery – Berms Inadequate



Photo 12 – Tank Battery – Berms Inadequate

Inspection Photos
Location Name: Craig 2
Location ID: 327437



Photo 13 – Tank Battery – Berms Inadequate



Photo 14 – Tank Battery – Berms Inadequate