

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



Entrance to location - Photo #06964



Location - Photo #06987

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



Location - Photo #06965



Location - Photo #06966

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



Location - Photo #06979



Location - Photo #06980

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



Location - Photo #06985



NE corner of location - Photo #06998

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



SE corner of location - Photo #06999



Failure to maintain chemical BMP/chemical tank
containment ¾ full of fluid - Photo #06972

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/2-10 PAD

Location ID: 334507

Date: 10/2/2024



Loose barbed wire/wildlife hazard - Photo #07002



Loose barbed wire/wildlife hazard - Photo #07007