

Inspection Photos


Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Entrance to location - Photo #06426



Location - Photo #06437

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Location - Photo #06427



Location - Photo #06432

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Location - Photo #06436



SW corner of location - Photo #06451

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



SE corner of location - Photo #06452



NE corner of location - Photo #06453

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Loose barbed wire/wildlife hazard - Photo #06445



Loose barbed wire/wildlife hazard - Photo #06447

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Loose barbed wire/wildlife hazard - Photo #06454



Debris - Photo #06455

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SESW

Location ID: 324200

Date: 9/30/2024



Debris - Photo #06456



Debris - Photo #06457