

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/3/2024



Location Entrance – Photo #03925



Wellheads – Photo #03935

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/3/2024



Separators – Photo #03926



Tank Battery – Photo #03927



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/3/2024



Open-Ended Line – Photo #03929



Open-Ended Line – Photo #03934

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/3/2024



Paint is Peeling From Tank – Photo #03932



Rill Erosion on Lease Road – Photo #03937