

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo # 6463 Entrance to location



Photo # 6464 Location

Inspection Photos
Location: QB ENERGY PUCKETT-66S97W/25SWSW
Location ID: 324201
Date: 9/30/2024



Photo # 6468 Location



Photo # 6482 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo # 6500 NW corner of location



Photo # 6501 NE corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo #6507 SW corner of location



Photo # 6476 Loose barbed wire/wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo # 6479 Loose barbed wire/wildlife hazard



Photo # 6496 Loose barbed wire/wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo # 6490 Wildlife hazard



Photo # 6491 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/25SWSW

Location ID: 324201

Date: 9/30/2024



Photo # 6502 Debris



Photo # 6505 Debris