

Inspection Photos

September 25th, 2024

Operator: American Helium Operating - 10841

Location ID: 381614

Inspection Document #: 714001299

Dolores County, CO

Township: NENE 31 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pribble Unit 1
Location ID: 381614



9/25/24
+37.619958,-108.979501
243° SW

Photo 1. View of the project area with equipment that remains on location.

Inspection Photos
Location Name: Pribble Unit 1
Location ID: 381614

9/25/24
+37.728840,-109.466601
76° E



Photo 2. View of access road that remains unreclaimed.

Inspection Photos
Location Name: Pribble Unit 1
Location ID: 381614

9/25/24
+37.619958,-108.979501
8° N



Photo 3. View of fallow agriculture field that surrounds disturbance.