

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334427

Inspection Doc: 696206341

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 1: Photo 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



September 27, 2024



September 27, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 3: Photos taken from the southeast/east ends of the Location. Photo shows interim areas/slopes that are not progressing towards 1003 revegetation requirements; slopes remain predominantly bare; erosion degradation also observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 4: Photos examples showing Noxious weeds (Canada Thistle, photo left; Musk thistle, photo right) observed within the interim areas of the Location, and along access road. Weed management efforts are apparent, however plants observed are still alive.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334427



Photo 5: Photos examples showing interim areas on the west and east end of the location- Areas are progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources