

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 438499

Inspection Doc: 696206343

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 1: Photos taken from the north end of the tank battery facility, facing southeast and south. Photo provides overview of the battery facility pad.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 2: Temporary equipment connected to separators. Photo right shows fluids spilled within the equipments' containment BMP.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 3: Sediment trap / drain on the southwest corner of the battery facility pad.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



September 27, 2024

Photo 4: Photo taken from the Location entrance of the well pad location, facing southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 438499



Photo 5: Wildlife protection measures (metal mesh/netting) has not been maintained in proper functioning condition.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 6: Sediment trap/drain on south end of the well pad Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



September 27, 2024



September 27, 2024

Photo 7: Photos taken from the interim areas on the east end of the Location. Photos provide an overview of the revegetation, as well as examples showing Noxious weeds (Musk thistle, photo right) observed. Weed management efforts are apparent throughout the Location, however several weeds/plants observed are still alive.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 8: Canada thistle established within eastern interim areas of the Location. Weed management efforts are apparent throughout the Location, however several weeds/plants observed are still alive.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 9: Photos taken from the interim areas between the well pad and tank battery facility pads. Photos provide an overview of the revegetation, as well as examples showing Noxious weeds (Musk thistle, photo right) observed. Weed management efforts are apparent throughout the Location, however several weeds/plants observed are still alive.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 438499



Photo 10: Photos taken from the interim areas on the west end of the Location. Photos provide an overview of the revegetation, as well as examples showing Noxious weeds (Musk thistle, photo right) observed. Weed management efforts are apparent throughout the Location, however several weeds/plants observed are still alive.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources