

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 442549

Inspection Doc: 696206345

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 3: Sediment traps / drains located on the NW and SW ends of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 4: Photos taken from the interim areas on the east end of the Location. Photos provide an overview of the revegetation. Interim areas are progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 5: Photos taken from the interim areas between the Location. Photos examples showing Noxious weeds (Musk thistle) observed. Weed management efforts are apparent throughout the Location, however several weeds/plants observed are still alive.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 6: Pipe equipment stored on the Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 7: Photos show stained soils observed around wells on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 8: Photos show stained soils observed around wells on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 442549



Photo 9: Photo shows line at tank missing cap/plug.