

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334426

Inspection Doc: 696206347

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



September 27, 2024



September 27, 2024

Photo 1: Photos taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 3: Photos taken from the interim areas on the southeast end of the Location. Photos show erosion logs have not been maintained in proper functioning condition. Erosion degradation due to runoff observed on slopes. Additional stormwater management effort required; additional reclamation efforts advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 5: Photos taken from the north end of the Location. Photo shows slopes are bare and unstabilize soils. Additional reclamation efforts required; BMPs to stabilize slopes, minimize erosion, degradation and sediment transport also required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 7: Photo shows lines at tanks missing cap/plug.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 8: Various trash/debris/unused equipment stored within tank battery containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



Photo 9: Various trash/debris/unused equipment stored within tank battery containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 334426



September 27, 2024

Photo 10: BMPs to stabilize working pad surface show signs of disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources