

# Inspection Photos

09/27/2024

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 449070

**Inspection Doc:** 696206352

Mesa County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



**Photo 1:** Photos taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



**Photo 3:** Photos examples of the interim areas. Vegetation appears to be progressing towards 1003 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



**Photo 4:** Lines at tanks missing cap/plug.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



**Photo 5: Unused equipment / debris.**



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 449070



September 27, 2024

**Photo 6: Erosion log in disrepair.**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources