

Inspection Photos

09/27/2024

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452797

Inspection Doc: 696206354

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 1: Photos taken from the location entrance on the west end of the Location. Photos provide an overview of the Location from north to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 2: Photos examples of the interim areas. Vegetation appears to be progressing towards 1003 standards. Though weeds were observed, ongoing weed management efforts are apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 3: Pipe equipment stored on Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 452797



Photo 4: Wildlife protection netting/fence in disrepair.