

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/3/2024



South End of Location – Photo #03956



Wellheads – Photo #03957

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/3/2024



Separators – Photo #03959



Tank Battery – Photo #03958

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/3/2024



Open-Ended Line on Separator – Photo #03960

