

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6559 Entrance to location




Photo # 6579 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6560 Location




Photo # 6565 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6576 Location



Photo # 6589 SW corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6590 SE corner of location



Photo # 6573 Wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6584 Open ended load line



Photo # 6575 Debris



Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/36NWSE

Location ID: 324208

Date: 9/30/2024



Photo # 6586 Debris



Photo # 6596 Unmarked deadman