

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6849 Entrance to location




Photo # 6883 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6850 Location



Photo # 6851 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6872 Location



Photo # 6873 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6874 Location



Photo # 6875 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6876 Location



Photo # 6881 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6891 Location



Photo # 6825 Location



Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6919 NE corner of location



Photo # 6922 NW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6923 SW corner of location



Photo # 6889 Open tank port/wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6890 Open tank port/wildlife hazard



Photo # 6914 Debris

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6915 Debris



Photo # 6916 Debris

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/23-13 PAD

Location ID: 334536

Date: 10/1/2024



Photo # 6917 Debris



Photo # 6918 Debris