

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad
Location ID: 324016



**Location Overview: Location is within Black Bear Habitat area
& in close proximity to High Priority/NSO Habitat areas.
Location is within Rule 411a Surface Water External Buffer.
Section/Township/Range: 7 7S93W**



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad
Location ID: 324016



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad
Location ID: 324016



Oct 2, 2024 at 12:36:33 PM

Photo # 3276 Erosion & transport of sediment off location /insufficient BMP's



Oct 2, 2024 at 12:36:37 PM

Photo # 3277 Erosion & transport of sediment off location /insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YUBERG RU 12-7 Pad
Location ID: 324016



**Photo # 3278 Erosion & transport of sediment off location
/insufficient BMP's**