

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 12-7 Pad

Location ID: 324016



Oct 2, 2024 at 12:35:18 PM



Oct 2, 2024 at 12:37:44 PM

Photo # 3265 From entrance to location

Photo # 3266 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad

Location ID: 324016



Photo # 3267 Location



Photo # 3268 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad

Location ID: 324016



Photo # 3269 Location



Photo # 3270 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 12-7 Pad

Location ID: 324016



Photo # 3271 Improperly marked deadman



Photo # 3272 Same improperly marked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 12-7 Pad

Location ID: 324016



Photo # 3273 Improperly marked deadman



Photo # 3274 Same improperly marked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 12-7 Pad

Location ID: 324016



Photo # 3275 Netting/wildlife protection on chemical tank & containment needs maintenance