

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HENRY-67S95W/3SWNW

Location ID: 334731

Date: 10/7/2024



Location Entrance – Photo #03977



Wellheads – Photo #03978

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HENRY-67S95W/3SWNW

Location ID: 334731

Date: 10/7/2024



Separators – Photo #03984



Tank Battery – Photo #03980

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, HENRY-67S95W/3SWNW

Location ID: 334731

Date: 10/7/2024



Ancillary Equipment – Photo #03983



Illegible Tank Label – Photo #03982