

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad
Location ID: 323942



**Location Overview: Location is within Black Bear Habitat area
& in close proximity to High Priority/Density Habitat areas.
Location is in close proximity to Rule 411a Surface Water
External Buffer.**

Section/Township/Range:

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad
Location ID: 323942



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad
Location ID: 323942



Photo # 3073 Ditch needs maintenance/ditch is full of sediment & sediment is being transported onto the lease road (on lease road approximately 1/10th to 2/10th of a mile from location)



Photo # 3074 Ditch needs maintenance/ditch is full of sediment & sediment is being transported onto the lease road (on lease road approximately 1/10th to 2/10th of a mile from location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad
Location ID: 323942



Photo # 3075 Ditch needs maintenance/ditch is full of sediment & sediment is being transported onto the lease road (on lease road approximately 1/10th to 2/10th of a mile from location)



Photo # 3076 Ditch needs maintenance/ditch is full of sediment & sediment is being transported onto the lease road (on lease road approximately 1/10th to 2/10th of a mile from location)