

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3057 From entrance to location



Photo # 3058 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942




Photo # 3059 Location



Photo # 3060 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3061 Location

Photo # 3062 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3063 Location



Photo # 3064 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3065 Location



Photo # 3066 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3067 Location



Photo # 3068 Staining near wellhead

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



Photo # 3069 Staining near wellhead



Photo # 3070 Staining near wellhead

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Youberg RU 22-7 Pad

Location ID: 323942



**Photo # 3071 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 3072 PRV vent line does not comply with CECMC pressure safety device rules**