

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403901384

Date Received:
08/29/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10503
Name of Operator: RED HAWK PETROLEUM LLC
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Charles Hinojosa</u>		<u>chinojosa@pedevco.com</u>
<u>Kelsi Welch</u>		<u>kelsi.welch@iptwell.com</u>
<u>Erin Ekblad</u>		<u>eekblad@pedevco.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306609
Inspection Date: 08/08/2024 FIR Submit Date: 07/30/2024 FIR Status: _____

Inspected Operator Information:

Company Name: RED HAWK PETROLEUM LLC Company Number: 10503
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 424707

Location Name: Planck Number: 1-14H County: WELD
Qtrqtr: NENE Sec: 14 Twp: 8N Range: 62W Meridian: 6
Latitude: 40.668091 Longitude: -104.279604

FACILITY - API Number: 05-123-00 Facility ID: 424715

Facility Name: Planck Number: 1-14H
Qtrqtr: NENE Sec: 14 Twp: 8N Range: 62W Meridian: 6
Latitude: 40.668091 Longitude: -104.279604

CORRECTIVE ACTIONS:

1 CA# 197624

Corrective Action: Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved. Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required.

Date: 08/19/2024

Response: CA COMPLETED

Date of Completion: 08/19/2024

Operator Comment: The well has been shut in while operations and equipment are being evaluated and reviewed to ensure full compliance. All applicable forms and documentation will be provided and/or updated prior to returning the well to production.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 197625

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 08/23/2024

Response: CA COMPLETED

Date of Completion: 08/23/2024

Operator Comment: All valves, pipes, fittings, and Production Facilities have been securely fastened. Stained soil has been removed & properly disposed of in accordance with 905.e.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please process this FIRR in place of FIRR doc #403895535. A request to delete the aforementioned FIRR has been sent to the inspector as of 8/27/2024.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch Signed: _____

Title: Permitting & Compliance Date: 8/29/2024 10:47:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403901384	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files