

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403916978

Date Received:
09/11/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------------|---------------------|---------------------------------|
| <u>SCHNEIDER, JEFF</u> | <u>970-867-9437</u> | <u>jeff@schneiderenergy.com</u> |

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201526
Inspection Date: 08/19/2024 FIR Submit Date: 08/21/2024 FIR Status: _____

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC Company Number: 76840
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 313900

Location Name: KNAPPE-66N60W Number: 7SWSW County: _____
Qtrqtr: SWS Sec: 7 Twp: 6N Range: 60W Meridian: 6
W
Latitude: 40.497786 Longitude: -104.145083

FACILITY - API Number: 05-087- -00 Facility ID: 313900

Facility Name: KNAPPE-66N60W Number: 7SWSW
Qtrqtr: SWS Sec: 7 Twp: 6N Range: 60W Meridian: 6
W
Latitude: 40.497786 Longitude: -104.145083

CORRECTIVE ACTIONS:

1 CA# 197889

Corrective Action: Comply with Rule 1004. Original corrective action date of 08/23/2023 (when the location was first observed out of compliance) remains. Date: _____

Response: CA COMPLETED Date of Completion: 09/07/2024

Operator Comment: Removal of equipment completed. Picture attached. Operator is actively working to comply with Rule 1004. for the final reclamation and recontour of the P&A'd location.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Removal of equipment completed. Picture attached. Operator is actively working to comply with Rule 1004. for the final reclamation and recontour of the P&A'd location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed: _____

Title: Regulatory Compliance

Date: 9/11/2024 11:53:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|------------------------|--------------------------|
| 403916978 | FIR RESOLUTION SUBMITTED |
| 403917006 | Debris Removal Photo |

Total Attach: 2 Files