

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403933477

Date Received:

09/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dolezal, Pat

pat.dolezal@ownresources.com

Krystal Heibel

krystal.heibel@state.co.us

Kyle Waggoner

kyle.waggoner@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100398

Inspection Date: 09/10/2024

FIR Submit Date: 09/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 304627

Location Name: STALLINGS WATER
DISPOSAL WEL-61N47W

Number: 12NENE

County: YUMA

Qtrqtr: NENE Sec: 12 Twp: 1N Range: 47W Meridian: 6

Latitude: 40.073550 Longitude: -102.569540

FACILITY - API Number: 05-125- -00

Facility ID: 269493

Facility Name: STALLINGS WATER
DISPOSAL WELL

Number: 6-12

Qtrqtr: NENE Sec: 12 Twp: 1N Range: 47W Meridian: 6

Latitude: 40.073550 Longitude: -102.569540

CORRECTIVE ACTIONS:

1 CA# 198828

Corrective Action: Install sign to comply with Rule 605.h.

Date: 12/18/2024

Response: CA COMPLETED

Date of Completion: 09/10/2024

Correct signage was posted at partially buried tank on day of inspection. It is actually in picture of partially buried tank that were attached with FIR. Please see attached photo of same signage.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 198829

Corrective Action: Repair and remove holes around wellhead, per Rule 603.o.

Date: 10/27/2024

Response: CA COMPLETED

Date of Completion: 09/24/2024

Operator
Comment: Animal holes around wellhead, along metal secondary containment and along partially buried tank have been properly removed. Please see attached photo. Operator requests clarification from inspector as to what part of Rule 603.o that was in violation

ECMC Decision:

ECMC
Representative:

3 CA# 198830

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 10/17/2024

Response: CA COMPLETED

Date of Completion: 09/24/2024

Operator
Comment: Piping from partially buried tank has been properly secured for normal daily operations.

ECMC Decision:

ECMC
Representative:

4 CA# 198831

Corrective Action: Comply with Rule 902.b to install or repair wildlife protection equipment.

Date: 11/17/2024

Response: CA COMPLETED

Date of Completion: 09/24/2024

Operator
Comment: Day tank and containment have been removed from location

ECMC Decision:

ECMC
Representative:

5 CA# 198832

Corrective Action: In accordance with Rule 913.e.(3), Operator shall submit a Form 27 Supplemental quarterly (every 90 days) to remediate any spill/release and/or to close the remediation project.

Date: 10/17/2024

Response: CA COMPLETED

Date of Completion: 09/24/2024

Operator
Comment: Location of SWD is not included in remediation project 30284. Operator is working to update Form 27 quarterly reporting.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Pat Dolezal

Signed:

Title: Regulatory Specialist

Date: 9/26/2024 7:38:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403933477	FIR RESOLUTION SUBMITTED
403935124	Location photo
403935125	Location photo
403935126	Location photo
403935127	Location photo
403935128	Location photo
403935130	Location photo
403935133	Location photo

Total Attach: 8 Files