

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403942670

Date Received:  
10/02/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 24500

Name of Operator: PADCO LLC

Address: 16508 ARMINTA STREET

City: VAN NUYS State: CA Zip: 91406

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

RICHMOND, DAN

dan@dsrinc.net

BROTHERTON, ANDREA

abrotherton@136elcamino.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708200244

Inspection Date: 05/15/2023

FIR Submit Date: 05/18/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: PADCO LLC

Company Number: 24500

Address: 800 W 6TH STREET SUITE 1010

City: LOS ANGELES State: CA Zip: 90017

#### LOCATION - Location ID: 317233

Location Name: FASSLER-62N53W Number: 32NENE County: \_\_\_\_\_

Qtrqtr: NENE Sec: 32 Twp: 2N Range: 53W Meridian: 6

Latitude: 40.101665 Longitude: -103.324694

#### FACILITY - API Number: 05-121- -00 Facility ID: 317233

Facility Name: FASSLER-62N53W Number: 32NENE

Qtrqtr: NENE Sec: 32 Twp: 2N Range: 53W Meridian: 6

Latitude: 40.101665 Longitude: -103.324694

### CORRECTIVE ACTIONS:

1 CA# 171140

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b.

Date: 05/29/2023

Response: CA COMPLETED

Date of Completion: 05/29/2023

Operator  
Comment:

Wildlife protection devices installed. Per Inspection on 6/3/2024, Document #711900812, inspection was "Satisfactory".

ECMC Decision: \_\_\_\_\_

--

Date: 10/2/2024 8:08:10 AM

Total Attach: 1 Files